

coreboot - Bug #104

Bug # 102 (Resolved): Enabling TPM under coreboot causes ACPI error and Linux kernel panic

Introduce architecture specific TPM acpi path (LPCB/LIBR)

03/29/2017 12:56 PM - Philipp Deppenwiese

Status:	New	Start date:	03/29/2017
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:			
Description			
Hey,			
sorry. I had no time until now to fix it.			
The problem is that https://review.coreboot.org/#/c/18522/ is missing for each platform.			
I am not happy with this solution maybe pointing out the architecture based LPC ACPI path would make things much easier.			
BG, Zaolin			