Issues

#	Project	Tracker	Status	Priority	Category	Subject	Assignee	Updated
499	coreboot	Bug	New	Normal		coreboot will not boot edk2 on Lenovo T440p with CONFIG_RESOURCE_ALLOCATION_TOP_DOWN enabled, cannot disable this setting during build	Nico Huber	04/17/2024 04:24 PM
355	flashrom	Feature	Response Needed	Normal	Release prep	Querying functions with meson integration	Nico Huber	10/31/2024 02:38 AM
288	coreboot	Bug	New	Normal		Type mismatch spots found by undefined behavior sanitizer	Nico Huber	01/05/2021 05:13 AM
287	coreboot	Bug	New	Normal		libgfxinit bootsplash.jpg loaded as BGR instead of RGB on Thinkpad x230	Nico Huber	11/09/2020 11:19 AM