

Issues

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated
56	coreboot	Feature	New	Normal	16GB DIMM support on Sandy/Ivy Bridge		08/11/2017 07:13 AM
138	coreboot	Bug	New	Normal	[ACPI] Name already exists in scope (TEVT) (IASL 20170728)		09/04/2017 05:30 PM
331	coreboot	Feature	New	Normal	Add detail wiki how to use oxford serial card?		12/30/2021 11:32 PM
356	flashrom	Feature	New	Normal	Add GD25Q256D from downstream	Anastasia Klimchuk	05/22/2022 11:35 AM
122	coreboot	Feature	New	Normal	Add intel sunrise management controller to ME device list for intelmetool		06/11/2017 10:33 AM
20	coreboot	Feature	In Progress	Normal	Add make target to check if toolchain is up to date	Martin Roth	01/07/2016 06:26 PM
212	coreboot	Feature	New	Normal	Add more gerrit plugins	Patrick Georgi	06/18/2020 09:00 PM
214	coreboot	Feature	New	Normal	Add openlibm to libpayload		06/19/2019 06:46 PM
329	coreboot	Feature	New	Normal	Add progress feature so it doesn't look "hung" when running make on slow internet connections		12/30/2021 11:25 PM
328	coreboot	Feature	New	Normal	Add RAM disk/filesystem in SPI flash for tianocore		03/23/2022 08:20 PM
251	coreboot	Bug	New	Normal	Add SD card detect GPIO in jsrvp devicetree	Aamir Bohra	05/21/2020 07:16 AM
357	flashrom	Feature	In Progress	Normal	Add Spansion S25FL512S	Nico Huber	05/24/2022 01:41 PM
330	coreboot	Feature	New	Normal	Add support for the red oxford debug card 1415:c120		12/30/2021 11:27 PM
105	coreboot	Bug	New	Normal	Add timeouts to nehalem raminit		07/18/2017 01:17 PM
377	flashrom	Feature	New	Normal	Add WP to struct tested		05/04/2022 08:58 AM
279	coreboot	Bug	New	Normal	All hp snb_ivb_laptops: Windows 10 & 7 BSOD	Iru Cai	10/03/2020 01:11 PM
98	coreboot	Bug	New	Normal	[AMD Family 10h/15h] CPU model printed with just spaces		03/02/2017 03:37 PM
285	coreboot	Bug	New	Normal	Asus A88XM-E: xHCI USB ports only with USB 1.x speed		10/19/2020 11:56 AM
221	coreboot	Bug	New	Normal	ASUS KCMA-D8 doesn't POST reliably when CMOS is completely cleared of vendor data		07/19/2019 01:26 PM
92	coreboot	Bug	New	Normal	Asus KGPE-D16 does not reboot out of some payload		01/31/2017 06:09 PM
101	coreboot	Bug	New	Normal	Asus M2V fails to boot to payload		04/14/2017 06:08 AM
325	coreboot	Bug	New	Normal	Asus P5QL-EM: NVIDIA card in PCIe X1 port not working		12/03/2021 04:56 PM
206	coreboot	Feature	New	Normal	Automate FMAP generation	Patrick Georgi	06/05/2019 06:01 PM
236	coreboot	Feature	New	Normal	Automatically run the bloblator for a series of blob configurations		09/09/2019 08:36 PM
61	coreboot	Bug	Response Needed	Normal	Bluetooth light on X200		06/08/2017 10:30 AM
30	coreboot	Bug	New	Normal	board-status allows invalid uploads		02/04/2016 09:52 PM
198	coreboot	Feature	New	Normal	board_status replacement		02/14/2019 08:50 AM
49	coreboot	Bug	New	Normal	board_status.sh does not check git identity		07/08/2020 05:34 PM
28	coreboot	Feature	New	Normal	board-status should reject duplicate uploads		03/24/2016 07:18 AM
29	coreboot	Feature	New	Normal	board-status should reject uploads with incorrect DMI string		02/03/2016 09:24 PM

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated
15	coreboot	Bug	In Progress	Normal	board-status uploads incorrect reports if config not found	Patrick Georgi	12/18/2015 06:37 PM
244	coreboot	Bug	New	Normal	Bootblock size inflated by over 1000%		01/30/2020 10:39 AM
211	coreboot	Feature	New	Normal	Build branches with branch toolchain	Patrick Georgi	06/05/2019 05:59 PM
239	coreboot	Bug	New	Normal	Build fails: No rule to make target pxe rom, but file exists		10/30/2019 06:15 AM
268	coreboot	Bug	New	Normal	Building Chrome EC within coreboot requires libftdi for no good reason		07/06/2020 08:48 AM
199	coreboot	Feature	New	Normal	build-test "the Documentation"		02/14/2019 08:49 AM
146	coreboot	Bug	New	Normal	build/util/kconfig/zconf.tab.o: file not recognized: File truncated		10/23/2017 08:06 PM
281	coreboot	Bug	New	Normal	cbfs stage loading encoding is not endian safe.		10/09/2020 12:11 AM
139	coreboot	Bug	New	Normal	cbfstool's -b argument is size checked before compression		09/10/2017 01:54 AM
117	coreboot	Bug	New	Normal	cbmem ringbuffer is broken		05/17/2017 08:37 PM
94	coreboot	Bug	New	Normal	cbmem time stamps incorrectly displayed on Asus KGPE-D16		01/31/2017 06:18 PM
33	coreboot	Bug	New	Normal	cbmem utility fails on newer linux kernels "Failed to mmap /dev/mem: Resource temporarily unavailable"		03/08/2016 10:54 PM
125	coreboot	Bug	New	Normal	Checkpatch does not respect https://www.coreboot.org/Git#Commit_messages		06/25/2017 10:25 AM
369	flashrom	Feature	New	Normal	Check Spansion chips definitions		04/28/2022 03:05 AM
375	flashrom	Feature	New	Normal	Check the right chipset is selected for Intel Emmitsburg PCH	David Hendricks	05/20/2022 10:42 PM
371	flashrom	Feature	New	Normal	Check XMC spi flash chips definitions		04/28/2022 03:13 AM
294	coreboot	Feature	New	Normal	clang-format doesn't support wrapping single-statement conditional blocks in braces		02/18/2021 09:39 AM
368	flashrom	Cleanup	New	Normal	Code style review for s25f chips infrastructure	Nikolai Artemiev	05/06/2022 07:00 AM
183	coreboot	Feature	New	Normal	Collection of ideas for GSoC and similar		01/21/2020 03:00 PM
115	coreboot	Feature	New	Normal	Consolidate Intel ICH7..PCH9 PIRQ configuration		05/31/2018 09:49 AM
55	coreboot	Bug	New	Normal	copy lzint decompress from phnxsplit into python phonix_extract		05/18/2016 10:59 PM
200	coreboot	Feature	New	Normal	Copy Paste detector		02/14/2019 08:56 AM
310	coreboot	Bug	Response Needed	Normal	Coreboot 4.14 fails on a Lenvovo T440p	Angel Pons	09/04/2021 08:09 AM
241	coreboot	Bug	New	Normal	Coreboot build fails when GRUB2 is selected as payload		10/31/2019 02:09 PM
238	coreboot	Bug	New	Normal	coreboot.rom containing big-endian code has little-endian encoded fmap headers.		10/24/2019 06:47 PM
225	coreboot	Feature	New	Normal	Create a datasheets site	Patrick Georgi	08/28/2019 05:18 PM
298	coreboot	Feature	New	Normal	Create a file configs/README		03/07/2021 06:57 PM
180	lava	Bug	New	Normal	create a gold version of (coreboot + linuxboot)		11/10/2018 09:52 PM
181	lava	Bug	New	Normal	create a lava job with linuxboot + write to hdd image		11/10/2018 09:56 PM
57	coreboot	Feature	Feedback	Normal	Create build rule for ASUS E35M1-I Deluxe		06/19/2016 06:51 AM

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated
220	coreboot	Feature	New	Normal	Create tooling to regularly ping MAINTAINERS	Patrick Georgi	07/18/2019 01:26 PM
309	coreboot	Bug	New	Normal	crossgcc: Handle missing tarballs in download step		05/29/2021 03:43 PM
316	coreboot	Bug	New	Normal	[crossgcc] Toolchain building for older Versions broken		08/24/2021 01:33 AM
308	coreboot	Cleanup	New	Normal	Deal with walkcbfs_asm		04/28/2021 09:02 AM
245	coreboot	Feature	New	Normal	Define scope of technical writing		12/04/2019 06:48 PM
319	coreboot	Feature	New	Normal	denverton_ns: Add ASL to support Linux pinctrl driver (GPIO controller)		09/02/2021 10:43 AM
318	coreboot	Bug	New	Normal	denverton_ns: Fix MRC cache write		01/24/2022 06:57 PM
142	coreboot	Feature	New	Normal	Detect different GCC versions		10/09/2017 03:07 PM
4	coreboot	Feature	New	Normal	Documentation for coreboot's public interface		11/18/2015 06:14 PM
295	coreboot	Feature	New	Normal	Documentation: include common parts	Alexey Vazhnov	03/07/2021 06:28 PM
359	flashrom	Documentation	New	Normal	Document how spireadmode param works in sb600spi	Edward .	05/06/2022 04:52 AM
360	flashrom	Documentation	New	Normal	Document lspcon_i2c_spi.c programmer		04/28/2022 01:27 AM
354	flashrom	Documentation	New	Normal	Document meson build for release		04/28/2022 12:40 AM
358	flashrom	Documentation	New	Normal	Document raiden_debug_spi.c programmer	Edward .	05/06/2022 04:50 AM
361	flashrom	Documentation	New	Normal	Document realtek_mst_i2c_spi programmer	Peter Marheine	05/06/2022 05:36 AM
215	coreboot	Support	New	Normal	Document the compressed image for AMD's F17h processors	Marshall Dawson	06/25/2019 03:27 PM
216	coreboot	Support	New	Normal	Document the PSP binaries for the blobs repo	Marshall Dawson	06/26/2019 04:42 PM
39	coreboot	Feature	New	Normal	Enable OS-level flashing of coreboot for ThinkPad T410/X201		08/10/2017 08:49 AM
232	coreboot	Feature	New	Normal	Enhance the blobolator		09/09/2019 08:13 PM
235	coreboot	Feature	New	Normal	Enhance trace analysis for the blobolator		09/09/2019 08:30 PM
233	coreboot	Feature	In Progress	Normal	Ensure the blobolator works on real hardware		02/04/2020 01:09 PM
384	flashrom	Bug	New	Normal	Error accessing ICH RCRB		05/22/2022 06:40 PM
300	coreboot	Bug	New	Normal	Error building coreboot for t440p		09/04/2021 08:14 AM
223	coreboot	Bug	New	Normal	Errors compiling: No Video on Thinkpad x220 with 4.10		07/30/2019 08:43 AM
46	coreboot	Bug	New	Normal	F2A85-M reports false temperatures		04/25/2016 07:10 PM
293	coreboot	Bug	New	Normal	Fails to build with LLVM/clang 11		02/15/2021 09:59 PM
343	coreboot	Bug	New	Normal	Fails to load GRUB payload: CPU Index 0 - APIC 0 Unexpected Exception:6 @ 10:00009016 - Halting		05/10/2022 01:33 PM
367	flashrom	Bug	In Progress	Normal	Fix libpci usage	Nico Huber	05/23/2022 01:28 PM
370	flashrom	Feature	New	Normal	Fix sb600spi	Edward .	05/06/2022 04:51 AM
163	coreboot	Bug	New	Normal	GA-B75M-D3H: Unstable with external video card		06/07/2018 05:32 PM

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated
165	coreboot	Bug	New	Normal	[ga-g41m-es2l] [coreboot 4.7] [grub] GRUB payload (launched from seabios) halts when trying to load linux kernel		05/05/2018 03:56 PM
229	coreboot	Feature	New	Normal	Gather requirements for a (PCI) resource allocator		09/09/2019 08:02 PM
306	coreboot	Cleanup	New	Normal	Get rid of CBFS master header		04/28/2021 08:58 AM
7	coreboot	Feature	In Progress	Normal	gnawty support based on acer cb3-111	Alexander Couzens	11/24/2015 08:55 PM
226	coreboot	Bug	New	Normal	google/cyan (and variants) broken by addition of C_ENVIRONMENT_BOOTBLOCK support for Braswell		08/29/2019 02:58 AM
90	coreboot	Bug	In Progress	Normal	GRUB fails to build under Debian testing		03/10/2017 06:04 PM
141	coreboot	Bug	New	Normal	GRUB payload hangs in HP Elitebooks	Iru Cai	05/15/2020 03:18 PM
213	coreboot	Feature	New	Normal	Have the bug tracker report activity to IRC and the mailing list	Patrick Georgi	06/05/2019 06:00 PM
335	coreboot	Bug	New	Normal	High priority bug causes bricking when tianocore and flash log console used together		01/04/2022 05:05 PM
350	coreboot	Bug	New	Normal	I225 PCIe device not detected on Harcuvar		04/25/2022 12:41 PM
21	coreboot	Bug	New	Normal	If a PCI device requests more memory space than is available, coreboot gives it to the device anyway, causing a board hang.		12/30/2015 06:34 PM
228	coreboot	Feature	New	Normal	Implement a proper (PCI) resource allocator		09/09/2019 08:08 PM
231	coreboot	Feature	New	Normal	Implement a test framework for resource allocators		09/09/2019 08:06 PM
230	coreboot	Feature	New	Normal	Implement a validator for resource allocations		09/09/2019 08:04 PM
280	coreboot	Feature	New	Normal	Implement EDKII_PEI_MP_SERVICES2_PPI for new FSP support in coreboot		09/28/2020 05:02 PM
234	coreboot	Feature	New	Normal	Implement filtering in the blobolator		09/09/2019 08:18 PM
210	coreboot	Feature	New	Normal	Improve board-status	Patrick Georgi	06/05/2019 05:59 PM
184	coreboot	Feature	New	Normal	Improve memtest86 fork		10/11/2021 06:56 AM
222	coreboot	Support	New	Normal	Include FSP stack and heap allocation requirement in FSP intergration guide	Aamir Bohra	07/26/2019 09:38 AM
191	coreboot	Bug	New	Normal	intelmetool error mapping physical memory		01/18/2019 08:02 AM
336	coreboot	Bug	New	Normal	Intelmetool makefile problem		02/03/2022 10:37 AM
252	coreboot	Feature	New	Normal	intel/skylake: Implement T states		01/29/2020 10:36 AM
104	coreboot	Bug	New	Normal	Introduce architecture specific TPM acpi path (LPCB/LIBR)		03/29/2017 12:56 PM
364	flashrom	Feature	New	Normal	Investigate whether clear_spi_id_cache() needs to be called before probing	Edward .	05/06/2022 04:56 AM
204	coreboot	Bug	New	Normal	ipxe build failure		10/29/2019 12:43 PM
86	coreboot	Bug	New	Normal	IRQ errors precede slow down of tape I/O, via SCSI and PCI/PCIe bridge	Timothy Pearson	06/06/2017 06:31 PM
332	coreboot	Bug	Response Needed	Normal	I selected payload Tianocore Upstream (not UEFIPayload) but its still using MrChromebox UEFIPayload files?		01/03/2022 06:54 PM
95	coreboot	Bug	New	Normal	Just 10 Cores visible with KFSN4-DRE with 2 HexCores		08/21/2017 11:49 PM
195	coreboot	Bug	New	Normal	KCMA-D8 "ACPI_BIOS_ERROR" BSoD Windows 10 installer		01/26/2019 06:33 PM

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated
151	coreboot	Bug	New	Normal	KCMA-D8 (and presumably other amdfam10/amdmct-based boards) fails to boot		12/31/2017 05:52 AM
193	coreboot	Bug	New	Normal	KCMA-D8 do_IRQ no handlers for vector		01/20/2019 08:44 PM
192	coreboot	Bug	New	Normal	KCMA-D8 iommu INVALID_DEVICE_REQUEST events		11/24/2019 02:38 PM
190	coreboot	Bug	New	Normal	KCMA-D8 RAM incompatibility that varies between Coreboot and Libreboot		01/13/2019 10:08 AM
196	coreboot	Bug	New	Normal	KCMA-D8 Slow boot without "USE_OPTION_TABLE" config option		02/14/2019 09:46 AM
118	coreboot	Bug	New	Normal	Kconfig defines symbols with unmet dependencies	Martin Roth	08/22/2017 03:11 PM
120	coreboot	Bug	New	Normal	kconfig_lint: False positives about duplicate choice symbols	Martin Roth	08/21/2017 11:30 PM
136	coreboot	Bug	New	Normal	kernel panic when poweroff after s3 resume in Arch Linux Live CD		08/20/2017 07:04 AM
130	coreboot	Bug	New	Normal	kernel: pci 0000:00:1e.0: bridge has subordinate 06 but max busn 09		07/18/2017 10:18 AM
148	coreboot	Bug	New	Normal	KGPE-D16 AMD-vi fails because combined sata is enabled		01/31/2018 04:45 PM
84	coreboot	Bug	New	Normal	kgpe-d16: coreboot and seabios boot with C1 and G1 slots empty, but grub hangs	Timothy Pearson	05/13/2017 09:46 PM
129	coreboot	Bug	New	Normal	KGPE-D16 fails to boot	Timothy Pearson	08/16/2017 11:50 AM
83	coreboot	Bug	New	Normal	KGPE-D16 - Only one (or zero) out of two PCIe 10 Gigabit ethernet devices functional	Timothy Pearson	06/06/2017 06:30 PM
284	coreboot	Bug	In Progress	Normal	lenovo/g505s: no IOMMU while using CONFIG_SECURITY_CLEAR_DRAM_ON_REGULAR_BOOT	Mike Banon	04/09/2021 08:30 AM
272	coreboot	Bug	New	Normal	Lenovo T60: GRUB command `halt` does not power off system		07/18/2020 06:58 PM
267	coreboot	Bug	New	Normal	Lenovo T60: Hang when decompression payload with resource allocator v4		04/12/2022 08:15 AM
266	coreboot	Bug	New	Normal	Lenovo T60: SeaBIOS often hangs during ATI/AMD VGA Option ROM execution		07/19/2020 05:23 AM
274	coreboot	Bug	New	Normal	Lenovo ThinkPad: Pressing power button in GRUB does not turn off system		07/19/2020 05:29 AM
73	coreboot	Bug	New	Normal	Lenovo X200 BT light is permanently off when UWB (3rd mPCIe slot) is enabled		06/08/2017 10:03 AM
74	coreboot	Feature	New	Normal	Lenovo X200 Mute button mutes with the EC, not in software		08/17/2017 02:26 PM
75	coreboot	Bug	New	Normal	Lenovo X200 Ultrabase often isn't detected unless woken with it attached		09/25/2016 10:22 AM
103	coreboot	Bug	New	Normal	[Lenovo X60] Playing sound with dock attached is garbled until stopped and restarted		03/22/2017 01:09 PM
76	coreboot	Feature	New	Normal	Let abuild work from config files instead of deriving everything by itself	Martin Roth	09/27/2016 05:48 PM
381	flashrom	Bug	New	Normal	libflashrom API should be versioned before a release	Evan Benn	05/13/2022 04:37 AM
287	coreboot	Bug	New	Normal	libgfxinit boot splash.jpg loaded as BGR instead of RGB on Thinkpad x230	Nico Huber	11/09/2020 11:19 AM
155	coreboot	Bug	New	Normal	libpayload: UHCI controller poll is broken	Patrick Rudolph	02/07/2018 07:19 AM
65	coreboot	Feature	New	Normal	Linux version of nvramcui		08/11/2016 05:20 PM
283	coreboot	Bug	New	Normal	Low uptime while using YABEL on g505s	Mike Banon	10/19/2020 04:05 PM
203	coreboot	Feature	New	Normal	LVFS support		06/09/2021 06:07 AM
282	coreboot	Bug	New	Normal	lz4 romstage loading is not endian safe.		10/13/2020 09:34 AM

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated
160	coreboot	Bug	New	Normal	mainboard intel kunimitsu with FSP 2.0		03/14/2018 02:32 PM
154	coreboot	Bug	New	Normal	mainboard: via: epia-m700: NULL pointer dereference (if SeaBIOS is payload)		01/19/2018 12:03 PM
168	coreboot	Bug	Feedback	Normal	make -j5 is incompatible with SeaBIOS payload		08/28/2019 12:32 PM
327	coreboot	Bug	New	Normal	MBOX3, OperationRegion (OPRG, SystemMemory, ASLS, 0x2000) causes windows uefi tianocore BSOD ACPI_BIOS_ERROR		04/23/2022 03:48 AM
379	flashrom	Feature	New	Normal	Merging Minipro code for TL866xx programmers		05/12/2022 11:25 AM
219	coreboot	Feature	New	Normal	MMIO fw_cfg for qemu-arm		07/07/2019 03:05 PM
175	coreboot	Bug	New	Normal	Most USB3 external disk enclosures do not work with coreboot on X230		07/20/2019 08:03 PM
292	coreboot	Feature	New	Normal	Move external code to src/vendorcode		02/12/2021 02:21 PM
124	coreboot	Bug	New	Normal	MRC cache problems on X220 with Atmel AT25DF641 chip		06/16/2017 01:35 PM
69	coreboot	Bug	New	Normal	Mute button doesn't issue a scancode with coreboot		04/24/2017 03:33 PM
264	coreboot	Bug	New	Normal	Native raminit fails to initialize half of installed RAM on ThinkPad W530		06/21/2020 01:06 PM
291	coreboot	Feature	New	Normal	Numerical array initializers aren't aligned numerically		02/12/2021 12:46 PM
186	coreboot	Feature	New	Normal	Nvidia optimus support		02/14/2019 08:53 AM
162	coreboot	Bug	New	Normal	nvrncui and coreinfo show "No coreboot tables were found." if the toolchain is made with "make crossgcc-x64".		08/15/2018 06:14 PM
133	coreboot	Bug	New	Normal	Only coreinfo title bar seen when loaded from GRUB		07/26/2017 11:15 AM
273	coreboot	Bug	New	Normal	Parallel build fails with `build/util/cbfstool/cbfstool: option requires an argument -- 'P'`		07/18/2020 08:01 AM
314	coreboot	Bug	New	Normal	Please disable 'administrator approval' on ticket.coreboot.org		07/30/2021 06:04 PM
366	flashrom	Bug	New	Normal	Possible division by zero for `freq` param in dummyflasher	Anastasia Klimchuk	05/06/2022 05:51 AM
270	coreboot	Bug	New	Normal	ppc64le: `src/arch/x86/include/arch/cpu.h:278:1: error: 'regparm' attribute directive ignored [-Werror=attributes]`		07/06/2020 12:44 PM
269	coreboot	Bug	New	Normal	ppc64le: `superiotool.h:12:10: fatal error: sys/io.h: No such file or directory`		07/06/2020 12:40 PM
14	coreboot	Feature	New	Normal	printout lenovo ec power cause register	Alexander Couzens	11/28/2015 07:52 PM
72	coreboot	Bug	New	Normal	Provide better a error message when trying to use missing blobs in a non-git tree		09/29/2016 07:46 PM
303	coreboot	Bug	New	Normal	qemu: Failure to build TianoCore UefiPayload		05/12/2021 08:02 AM
250	coreboot	Bug	New	Normal	QEMU i440fx: acpi LNXCPU:00: Failed to get unique processor _UID (0x0)		01/07/2020 11:34 PM
189	coreboot	Feature	New	Normal	QEMU mips support		12/08/2018 10:59 AM
187	coreboot	Feature	New	Normal	QEMU power9 support		12/08/2018 10:57 AM
197	coreboot	Feature	New	Normal	QEMU x86_64 support		02/14/2019 08:51 AM
355	flashrom	Feature	Response Needed	Normal	Querying functions with meson integration	Nico Huber	05/23/2022 11:12 PM
326	coreboot	Bug	New	Normal	raminit fails after 58188 review.coreboot.org		12/31/2021 06:51 AM

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated
353	flashrom	Feature	In Progress	Normal	Release v1.3	Anastasia Klimchuk	05/22/2022 10:47 PM
224	coreboot	Bug	New	Normal	Remove CONFIG_AMDFW_OUTSIDE_CBFS from Stoney Ridge	Marshall Dawson	08/08/2019 08:37 PM
299	coreboot	Bug	New	Normal	Restore/redirect https://review.coreboot.org/p/seabios.git so older versions still work		03/11/2021 04:49 PM
376	flashrom	Feature	New	Normal	Review mediatek_i2c_spi		04/28/2022 03:33 AM
255	coreboot	Support	New	Normal	Riscv booting Linux with OpenSBI		02/28/2020 04:07 PM
66	coreboot	Bug	New	Normal	rmodule_copy_payload() does not initialize unused memory	Aaron Durbin	05/16/2017 10:03 PM
100	coreboot	Bug	New	Normal	romstage only transferred with baud rate 1200 independent from configuration		12/09/2017 11:24 AM
324	coreboot	Support	New	Normal	samsung r580		01/05/2022 03:54 PM
262	coreboot	Bug	New	Normal	Sandy Bridge/IvyBridge: Only advertise supported MWAIT states as ACPI C states		02/21/2021 01:55 AM
80	coreboot	Bug	New	Normal	Screen garbled in Seabios, does not boot, Kernel panic (X60)		04/14/2017 01:04 PM
248	coreboot	Feature	New	Normal	SeaBIOS as secondary payload (after GRUB)		12/26/2019 09:44 PM
275	coreboot	Bug	New	Normal	Securely running ATI/AMD VGA Option ROM fails with `Unknown INT15 function 5f08!`		07/19/2020 06:53 AM
301	coreboot	Bug	New	Normal	soc/amd: gpio_bank_lib.asl: IASL remarks on inefficient creation of named objects		03/26/2021 07:24 AM
113	coreboot	Bug	New	Normal	soc/intel/skylake sets P*RC registers three times		05/10/2017 09:35 PM
261	coreboot	Feature	New	Normal	[soc/intel] Use a generic vr_config.c		06/15/2020 11:08 AM
88	coreboot	Bug	New	Normal	Some issues with coreboot on T420 (touchpad and phone jack)		04/28/2020 06:34 PM
202	coreboot	Feature	New	Normal	Some kconfig_lint warnings don't get posted to Gerrit		04/08/2019 10:03 PM
217	coreboot	Bug	New	Normal	spi flash cleanup		07/01/2019 08:59 PM
276	coreboot	Bug	New	Normal	SPI flash console output causes `SMM Handler caused a stack overflow`		07/19/2020 07:36 AM
372	flashrom	Feature	New	Normal	Support code for per-region file arguments	David Hendricks	05/21/2022 02:55 PM
307	coreboot	Feature	New	Normal	Support FMAP in SeaBIOS		04/28/2021 09:47 AM
349	coreboot	Support	New	Normal	support to add WINBOND W25Q256JW SPIROM		04/12/2022 08:14 AM
85	coreboot	Bug	New	Normal	Suspend does not work on the X220t		11/21/2017 08:07 PM
278	coreboot	Bug	New	Normal	T420: Legacy VGA display and external monitor issue		07/29/2020 10:23 AM
277	coreboot	Bug	New	Normal	T420: RAM module type information stored in flash		07/29/2020 10:47 AM
297	coreboot	Bug	New	Normal	T440P card reader is broken.		06/20/2021 02:20 PM
320	coreboot	Feature	New	Normal	T440p: Does not display fan RPM		09/04/2021 08:10 AM
259	coreboot	Bug	New	Normal	T440p: Tianocore unable to boot Windows 10 (MACHINE_CHECK_EXCEPTION)	Angel Pons	02/26/2021 07:57 PM
243	coreboot	Bug	New	Normal	T440P: Unable to initialize memory speeds above 1600 MT/s		01/30/2020 10:15 AM
121	coreboot	Bug	New	Normal	T520: Hangs in OS		11/07/2021 04:23 PM
378	flashrom	Feature	New	Normal	Testing for release v1.3		05/20/2022 12:34 AM

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated
380	flashrom	Cleanup	New	Normal	tests/lifecycle.c: Split up into compilation units	Anastasia Klimchuk	05/13/2022 01:23 AM
156	coreboot	Feature	New	Normal	[thinkpad] Implement battery recalibration in ACPI		06/06/2019 04:44 PM
289	coreboot	Bug	New	Normal	Thinkpad T410i does absolutely nothing		01/29/2021 09:01 AM
99	coreboot	Bug	New	Normal	Thinkpad T420: Bluetooth indicator light is always on		05/21/2017 06:05 AM
323	coreboot	Bug	New	Normal	thinkpad T60 expresscard support		12/02/2021 12:32 AM
108	coreboot	Feature	In Progress	Normal	thinkpad x1 carbon gen 1 remaining tasks	Alexander Couzens	01/24/2022 07:25 PM
152	coreboot	Bug	New	Normal	Thinkpad x220: express card not recognized unless present at the boot time		07/20/2019 08:34 PM
171	coreboot	Bug	New	Normal	Thinkpad X220: usb_always_on broken by 9554b26f9fd608		01/28/2019 09:27 PM
172	coreboot	Bug	New	Normal	Thinkpad X230 consumes about ~40% more battery energy idling with coreboot		08/25/2018 09:54 AM
159	coreboot	Bug	New	Normal	ThinkPad X230: Internal panel not works under Windows10		06/13/2018 07:59 PM
149	coreboot	Bug	New	Normal	tianocore fails with: Error: The specified tag is invalid		11/09/2017 06:24 PM
312	coreboot	Bug	In Progress	Normal	[Tianocore] gcc11: UefiPayloadPkg build fails	Matt DeVillier	01/28/2022 04:04 PM
237	coreboot	Bug	New	Normal	Tianocore payload displays blank screen on qemu, with X64 Exception Type - 00(#DE - Divide Error) CPU Apic ID - 00000000		09/18/2019 07:39 AM
333	coreboot	Bug	New	Normal	Tianocore - Virtualbox (manuall install to suppo or https://github.com/AdnanHodzic/displaylink-debian install causes /sbin/update-secureboot-policy --enroll-key to be run with no ability to cancel unless renamed the /sbin/update-secureboot-policy file		12/31/2021 05:27 AM
38	coreboot	Feature	New	Normal	tp_smapi support on ThinkPads	Alexander Couzens	01/02/2018 11:07 PM
254	coreboot	Bug	New	Normal	Trying to compile and run coreboot on qemu-riscv..		02/17/2020 04:11 PM
288	coreboot	Bug	New	Normal	Type mismatch spots found by undefined behavior sanitizer	Nico Huber	01/05/2021 05:13 AM
166	coreboot	Bug	New	Normal	UEFI MP Services		06/01/2018 04:05 PM
383	flashrom	Feature	New	Normal	Update Docker containers		05/22/2022 10:47 PM
382	flashrom	Documentation	New	Normal	Update Downloads page on the website		05/20/2022 12:29 AM
373	flashrom	Documentation	New	Normal	Update manpage that - can be filename for stdin		04/28/2022 03:24 AM
290	coreboot	Feature	In Progress	Normal	Use clang-format for the entire tree	Patrick Georgi	02/12/2021 02:21 PM
12	coreboot	Bug	New	Normal	Use of CONFIG_MAINBOARD_POWER_ON_AFTER_POWER_FAIL is a mess		12/04/2015 03:47 PM
365	flashrom	Feature	New	Normal	Variable size in dummy programmer	Anastasia Klimchuk	05/17/2022 11:43 PM
362	flashrom	Feature	In Progress	Normal	Verify block erasers are not missing for W25Q256.W	Nico Huber	05/23/2022 01:27 PM
19	coreboot	Bug	New	Normal	Violations of Coding guidelines: All objects should have fully qualified types (unsigned int instead of unsigned)		04/06/2016 10:36 PM
182	coreboot	Bug	New	Normal	W530 shuts down after reaching 101C with Turbo Boost and high loads		12/02/2018 10:30 PM

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated
27	coreboot	Bug	New	Normal	Windows doesn't like references in ACPI to objects that are only defined later		02/05/2016 03:49 AM
258	coreboot	Bug	New	Normal	X200: Resume from S3 undocks and breaks USB		02/28/2021 11:40 AM
112	coreboot	Bug	New	Normal	x201 doesn't work on master (57d912bacc)		05/08/2017 04:56 PM
36	coreboot	Bug	New	Normal	x201: stuck ec event		03/10/2016 09:32 PM
185	coreboot	Feature	New	Normal	x86_64 support on real hardware		12/08/2018 10:52 AM
374	flashrom	Bug	New	Normal	-x option filters only spaces when converting region names to file names		04/28/2022 03:27 AM
315	coreboot	Bug	New	Normal	Xorg/Wayland show black screen when system memory is 4GB or higher		08/04/2021 10:23 PM