

## coreboot - Bug #176

**src/vendorcode/intel/fsp1\_0/ivybridge\_i89xx/include/fspapi.h has a proprietary license**

10/19/2018 09:26 PM - Ian Kelling

<b>Status:</b> Closed	<b>Start date:</b> 10/19/2018
<b>Priority:</b> Normal	<b>Due date:</b>
<b>Assignee:</b>	<b>% Done:</b> 0%
<b>Category:</b>	<b>Estimated time:</b> 0.00 hour
<b>Target version:</b>	
<b>Description</b> fixed by <a href="https://review.coreboot.org/c/coreboot/+/28739">https://review.coreboot.org/c/coreboot/+/28739</a>	

### History

---

**#1 - 01/11/2019 01:49 PM - Arthur Heymans**

This code was dropped from the master branch so this can be closed.

**#2 - 01/14/2019 04:01 PM - Patrick Rudolph**

- Status changed from New to Closed

Code was dropped.