

Issues

#	Project	Tracker	Status	Priority	Category	Subject	Assignee	Updated
129	coreboot	Bug	New	Normal	board support	KGPE-D16 fails to boot	Timothy Pearson	08/16/2017 11:50 AM
86	coreboot	Bug	New	Normal	board support	IRQ errors precede slow down of tape I/O, via SCSI and PCI/PCIe bridge	Timothy Pearson	06/06/2017 06:31 PM
84	coreboot	Bug	New	Normal		kgpe-d16: coreboot and seabios boot with C1 and G1 slots empty, but grub hangs	Timothy Pearson	05/13/2017 09:46 PM
83	coreboot	Bug	New	Normal		KGPE-D16 - Only one (or zero) out of two PCIe 10 Gigabit ethernet devices functional	Timothy Pearson	06/06/2017 06:30 PM