

Issues

#	Project	Tracker	Status	Priority	Category	Subject	Assignee	Updated
461	coreboot	Feature	In Progress	Normal	chipset configuration	Replacing Haswell mrc.bin blob with free software	Angel Pons	03/12/2025 10:23 PM
449	coreboot	Bug	In Progress	Normal	board support	ThinkPad T440p fail to start, continous beeping & LED blinking	Angel Pons	02/07/2023 03:25 PM
311	coreboot	Bug	Resolved	Normal	board support	T410 PCIe Endpoints missing after flashing coreboot	Angel Pons	06/06/2021 01:59 PM
310	coreboot	Bug	Resolved	Normal		Coreboot 4.14 fails on a Lenvovo T440p	Angel Pons	10/14/2022 11:49 AM
305	coreboot	Bug	Closed	Normal	chipset configuration	Thermal sensors on Thinkpad X201 no longer working	Angel Pons	04/23/2021 10:27 PM
259	coreboot	Bug	New	Normal	board support	T440p: Tianocore unable to boot Windows 10 (MACHINE_CHECK_EXCEPTION)	Angel Pons	02/26/2021 07:57 PM