

coreboot - Bug #182

W530 shuts down after reaching 101C with Turbo Boost and high loads

11/29/2018 09:51 PM - Evgeny Zinoviev

Status:	New	Start date:	11/29/2018
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:			
Description			
A continuation of https://review.coreboot.org/c/coreboot/+29822 Attachments are decompiled DSDT and SSDTs from vendor BIOS.			

History

#1 - 12/02/2018 10:20 PM - Nico Huber

Actually, I was asking for coreboot dumps (vendor might even be illegal, idk).

#2 - 12/02/2018 10:30 PM - Evgeny Zinoviev

- File *dsdt.dsl* added

Files

File Name	Size	Date	Author
dsdt.dsl	526 KB	11/29/2018	Evgeny Zinoviev
ssdt1.dsl	1.88 KB	11/29/2018	Evgeny Zinoviev
ssdt2.dsl	22.8 KB	11/29/2018	Evgeny Zinoviev
ssdt3.dsl	768 Bytes	11/29/2018	Evgeny Zinoviev
ssdt4.dsl	13.9 KB	11/29/2018	Evgeny Zinoviev
ssdt6.dsl	10.8 KB	11/29/2018	Evgeny Zinoviev
ssdt5.dsl	19.8 KB	11/29/2018	Evgeny Zinoviev
ssdt7.dsl	2.12 KB	11/29/2018	Evgeny Zinoviev
ssdt8.dsl	16.2 KB	11/29/2018	Evgeny Zinoviev
ssdt9.dsl	5.6 KB	11/29/2018	Evgeny Zinoviev
dsdt.dsl	152 KB	12/02/2018	Evgeny Zinoviev