

## coreboot - Bug #249

### Clean up jasperlake\_rvp devictree

12/27/2019 05:46 AM - Aamir Bohra

<b>Status:</b>	New	<b>Start date:</b>	12/27/2019
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>	Aamir Bohra	<b>% Done:</b>	0%
<b>Category:</b>		<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>			
<b>Description</b>			
Current jasperlake_rvp mainboard CL: <a href="https://review.coreboot.org/c/coreboot+/37557">https://review.coreboot.org/c/coreboot+/37557</a> is based on copy from icelake_rvp . Once this is merged, devicetree needs to be cleaned up as per JSL SOC. This bug tracks further jasperlake_rvp mainboard devicetree cleanup			